

Abstract

In a method of carrying out continuous preparation processes on tightly meshing extruders rotating in the same sense such as twin-screw and multi-
5 shaft screw-type extruders, the extruder is operated at a screw speed of rotation of at least 800 rpm, accompanied with a simultaneous increase of the so-called "torque density" (M_d/a^3) of at least 11 Nm/cm³ and a volumetric ratio (D_a/D_i) of at least 1.5.

09043954-032798
B67250-456E4060